



## Mercedes-Benz 1317 / Bergingswagen / Euro 101 Laadkraan / Plateau / Bril / Lier / Hydraulische Oprijplaten

### General features

Brand	Mercedes-Benz
Model	1317
Subcategory	Tow-recovery
Odometer reading	180.195km
Color	Yellow
Condition	Used
General condition	Good
Fuel	Diesel



# Mercedes-Benz 1317 / Bergingswagen / Euro 101 Laadkraan / Plateau / Bril / Lier / Hydraulische Oprijplaten

## Technical specifications

Number of axes	2
Axis configuration	4x2
Transmission	Manual

## Accessories

- 2 pedal control
- 3rd valve
- 4rd valve
- 5rd valve
- Cabin
- Hosegroups
- Spotlight rear
- Spotlight front
- Heater
- Front window
- Rotating beacon
- Visor
- Toolbox
-